



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
May 21, 2008

Reviewed: TR

<b>Mine Name:</b> Rosebud	<b>Permit Number:</b> M/003/0026
<b>Operator Name:</b> Star Stone Quarries, Inc.	<b>Inspection Date:</b> March 19, 2008
<b>Inspector(s):</b> Lynn Kunzler	<b>Time:</b> 8:30 am
<b>Other Participants:</b> None	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Routine Inspection while in the area

**Inspection Summary:**

This site is considered active, even though there was no activity during this inspection. Activity has been occurring at both pits, with several hundred pallets of stone ready for shipping. Most garbage has been cleaned up. The trackhoe on site had a broken hydraulic line and had spilled a significant amount of oil on the ground. This will need to be cleaned up. Fuel storage has secondary containment with no fuel or oil barrels outside the secondary containment area.

The reclamation surety for this site is overdue for escalation.

Photos were taken to document site conditions.

**Conclusions and Recommendations:**

DOGM's bonding coordinator needs to contact this operator to initiate the surety escalation.  
Continue to monitor this site when in the area.

**Inspector's Signature** [Signature]

LK:pb

cc: Lon Thomas, Operator

Larry Garahana, BLM-SLC FO

✓ Ted Pearson, DOGM Bond Coordinator

O:\M003-BoxElder\M0030026-Rosebud\inspections\Insp-03192008.doc